



Technical Service Bulletin

Technical Service Bulletin: tsb102793	Released Date: 17-Apr-2008
Additional Step, Symptom Tree T021, Coolant Loss - Internal	

Additional Step, Symptom Tree T021, Coolant Loss - Internal

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises symptom tree T021, Coolant Loss - Internal, by adding a check for a coolant leak on the turbocharger housing.

Note : This is a product improvement and is not subject to campaign.

Coolant Loss - Internal

Last Modified: 17-Apr-2008
