



Technical Service Bulletin

Technical Service Bulletin: tsb102795	Released Date: 01-May-2008
Addition, Fault Code 951	

Addition, Fault Code 951

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic introduces the addition of Fault Code 951 to the Signature™, ISX and QSX15 Electronic Control System T&R Manual, Bulletin 3666259.

Cylinder Power Imbalance

Last Modified: 01-May-2008
