



Technical Service Bulletin

Technical Service Bulletin: tsb102845	Released Date: 16-May-2008
Symptom Tree t122 (Turbocharger Leaks Engine Oil or Fuel) Addition	

Symptom Tree t122 (Turbocharger Leaks Engine Oil or Fuel) Addition

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises symptom tree t122 (Turbocharger Leaks Engine Oil or Fuel). A check for turbocharger actuator cross shaft oil seal leakage was added to the end of the tree.

Turbocharger Leaks Engine Oil or Fuel

Last Modified: 16-May-2008
