



# Technical Service Bulletin

Technical Service Bulletin: tsb102884

Released Date: 07-Jul-2008

Lubricating Oil Pan Procedure, Install Section Revision

## Lubricating Oil Pan Procedure, Install Section Revision

### Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

The Service/Parts Topic revises the Install section in Procedure 007-025 Lubricating Oil Pan in Section 7. A step has been added to loosen and tighten the mounting capscrew in the number one location.

### Related Procedures

10-007-025-tr  
(/qs3/pubsys2/xml/en/procedures/10/10-007-025-tr.html)

Lubricating Oil Pan  
(/qs3/pubsys2/xml/en/procedures/10/10-007-025-tr.html)

Last Modified: 07-Jul-2008