



Technical Service Bulletin

Technical Service Bulletin: tsb102931

Released Date: 11-Jul-2008

Revision, Cylinder Liner Procedure

Revision, Cylinder Liner Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 001-028 (Cylinder Liner) in the K19 Service Manual, Bulletin 4021499. The Remove step has been revised to change the recommended cylinder liner removal service tool to Part Number 3163745.

Related Procedures

18-001-028-tr
(/qs3/pubsys2/xml/en/procedures/18/18-001-028-tr.html)

Cylinder Liner
(/qs3/pubsys2/xml/en/procedures/18/18-001-028-tr.html)

Last Modified: 11-Jul-2008