



Technical Service Bulletin

Technical Service Bulletin: tsb102942

Released Date: 02-Jul-2008

Engine Base Timing Procedure, Multiple Section Revisions

Engine Base Timing Procedure, Multiple Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 001-008 (Engine Base Timing) in Section 1 of the Service Manual, Signature™, ISX, and QSX15 Engines, Bulletin 3666239. This Service/Parts Topic adds a step for cleaning the Loctite™ residue from the camshaft nose after the camshaft gear has been removed. Information has also been added for inspecting the camshaft gear for cracking around the puller holes. A new step was also added for applying Loctite™ 609, Part Number 3823718, to the inside diameter of the camshaft gear before the gear is installed.

Related Procedures

10-001-088-tr
(/qs3/pubsys2/xml/en/procedures/10/10-001-088-tr.html)

Engine Base Timing
(/qs3/pubsys2/xml/en/procedures/10/10-001-088-tr.html)

Last Modified: 02-Jul-2008