



Technical Service Bulletin

Technical Service Bulletin: tsb103057

Released Date: 24-Sep-2008

Overhead Set (OBC) Procedure, General Information Section Revision

Overhead Set (OBC) Procedure, General Information Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the General Information Section in Procedure 003-006, Overhead Set (OBC), in the Troubleshooting and Repair Manual, QSK23 Series Engine, Bulletin 4021375.

Related Procedures

89-003-006
(/qs3/pubsys2/xml/en/procedures/89/89-003-006.html)

Overhead Set (OBC)
(/qs3/pubsys2/xml/en/procedures/89/89-003-006.html)

Last Modified: 24-Sep-2008