



Technical Service Bulletin

Technical Service Bulletin: tsb103184	Released Date: 11-Nov-2008
Symptom Tree t105 (Lubricating Oil Pressure Low) Revisions	

Symptom Tree t105 (Lubricating Oil Pressure Low) Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Symptom Tree t105 (Lubricating Oil Pressure Low) to add a differential pressure drop test and revise the tree to address oil filter plugging.
--

Lubricating Oil Pressure Low

Last Modified: 11-Nov-2008
