



Technical Service Bulletin

Technical Service Bulletin: tsb103262	Released Date: 21-Jan-2009
Fault Code 155, New	

Fault Code 155, New

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic introduces Fault Code 155.

Intake Manifold 1 Temperature - Data Valid but Above Normal Operational Range - Most Severe Level

Last Modified: 21-Jan-2009
