



Technical Service Bulletin

Technical Service Bulletin: tsb103372	Released Date: 25-Feb-2009
Fault Code 418 Addition	

Fault Code 418 Addition

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds Fault Code 418 (Water-In-Fuel Indicator - Data Valid but Above Normal Operational Range - Least Severe Level) to the Signature™, ISX, and QSX15 Electronic Control System Troubleshooting and Repair Manual, Bulletin 3666259.

Water-In-Fuel Indicator - Data Valid but Above Normal Operational Range - Least Severe Level

Last Modified: 25-Feb-2009
