



Technical Service Bulletin

Technical Service Bulletin: tsb103499

Released Date: 07-May-2009

Cylinder Head Procedure, Multiple Section Revisions

Cylinder Head Procedure, Multiple Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 002-004 (Cylinder Head) in Section 2 for K19 engines in Service Bulletin, K19, Bulletin 4021499.

The use of the injector protrusion gauge, Part Number 4919196, in the Assemble section has been corrected.

Related Procedures

18-002-004-tr
(/qs3/pubsys2/xml/en/procedures/18/18-002-004-tr.html)

Cylinder Head
(/qs3/pubsys2/xml/en/procedures/18/18-002-004-tr.html)

Last Modified: 07-May-2009