



Technical Service Bulletin: tsb103516

Released Date: 20-May-2009

Coolant Loss Troubleshooting Symptom Trees, Obsolescence and Revisions

## Coolant Loss Troubleshooting Symptom Trees, Obsolescence and Revisions

### Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

This Service/Parts Topic announces the obsolescence of Troubleshooting Symptom Tree t019 and the revision of Troubleshooting Symptom Trees t021 and t025. These changes improve troubleshooting logic for coolant loss.

The Coolant Loss Troubleshooting Symptom Tree t019 was removed because the tree steps are addressed in other, more applicable Troubleshooting Symptom Trees.

Revisions to Coolant Loss - Internal Troubleshooting Symptom Tree t021 include the following:

- Changes to the order of the steps
- Addition of a check for a leaking Auxiliary Power Unit
- Removal of the Pressure Test step
- Change in the final step that identifies the Cause as 'Base engine problem' and the Correction as 'Refer to Cummins Inc. and request additional technical assistance'.

Revisions to Coolant in the Lubricating Oil Troubleshooting Symptom Tree t025 include the following:

- Changes to the order of the steps
- Addition of a check for damaged injector o-rings or damaged sleeve
- Removal of the cylinder liner is corroded or cracked step
- Removal of the cylinder block is cracked or porous step
- Change in the final step that identifies the Cause as 'Base engine problem' and the Correction as 'Refer to Cummins Inc. and request additional technical assistance'.

Coolant Loss - Internal Coolant in the Lubricating Oil

Last Modified: 20-May-2009

