



Technical Service Bulletin

Technical Service Bulletin: tsb103579	Released Date: 21-Sep-2009
Symptom Tree t092 (Fuel in the Lubricating Oil), Cause and Correction Additions and Revision	

Symptom Tree t092 (Fuel in the Lubricating Oil), Cause and Correction Additions and Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic updates Symptom Tree t092 (Fuel in the Lubricating Oil) to improve troubleshooting logic. Steps have been moved and added to address the following:

- Fuel pump and injector checks were placed before fuel line restriction checks. The improved tree now places the fuel line restriction check prior to the fuel pump and injector checks.
- There was **not** a step to check the injectors for blown or missing plug balls. The improved tree now includes this check.

Fuel in the Lubricating Oil

Last Modified: 21-Sep-2009
