



Technical Service Bulletin

Technical Service Bulletin: tsb103793

Released Date: 09-Jun-2009

Cylinder Block Procedure, Inspect for Reuse Section Revision

Cylinder Block Procedure, Inspect for Reuse Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic informs the field of the addition of the main bearing bore diameter dimensions in the Inspect for Resuse section in Procedure 001-026 (Cylinder Block) in Section 1 of the Signature™, ISX, and QSX15 Service Manual, Bulletin 3666239.

Related Procedures

10-001-026-tr
(/qs3/pubsys2/xml/en/procedures/10/10-001-026-tr.html)

Cylinder Block
(/qs3/pubsys2/xml/en/procedures/10/10-001-026-tr.html)

Last Modified: 09-Jun-2009