



Technical Service Bulletin

Technical Service Bulletin: tsb103815

Released Date: 08-Jun-2009

Fuel Pump Procedure, Multiple Section Revisions

Fuel Pump Procedure, Multiple Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic updates the Install Section of Procedure 005-016 (Fuel Pump) in Section 5, to include a tightening sequence to the torque specifications.

Related Procedures

10-005-016
(/qs3/pubsys2/xml/en/procedures/10/10-005-016.html)

(/qs3/pubsys2/xml/en/procedures/10/10-005-016.html)

Last Modified: 08-Jun-2009