



Technical Service Bulletin

Technical Service Bulletin: tsb103832

Released Date: 05-Jun-2009

Service Tool Procedure, Cylinder Block Capscrew Thread Repair Service Tools Added

Service Tool Procedure, Cylinder Block Capscrew Thread Repair Service Tools Added

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 022-001_01 (Service Tools) to include the tool part numbers required to complete the cylinder head capscrew thread repair.

Related Procedures

10-022-001_01
(/qs3/pubsys2/xml/en/procedures/10/10-022-001_01.html)

Service Tools
(/qs3/pubsys2/xml/en/procedures/10/10-022-001_01.html)

Last Modified: 05-Jun-2009