



Technical Service Bulletin

Technical Service Bulletin: tsb103905

Released Date: 04-Aug-2009

Cooling System Procedure, Fill Section Revision

Cooling System Procedure, Fill Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revise the Fill section of Procedure 008-018 (Cooling System) in the Signature, ISX and QSX15 Service Manual, Bulletin 3666239.

The changes provide new information in the procedure regarding the location and type of manual bleed valve(s) or pipe plug(s) installed on certain chassis.

Related Procedures

10-008-018-tr
(/qs3/pubsys2/xml/en/procedures/10/10-008-018-tr.html)

Cooling System
(/qs3/pubsys2/xml/en/procedures/10/10-008-018-tr.html)

Last Modified: 04-Aug-2009