



Technical Service Bulletin

Technical Service Bulletin: tsb103951

Released Date: 30-Sep-2009

Cylinder Head and Lubricating Oil System Service Tool Revisions

Cylinder Head and Lubricating Oil System Service Tool Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedures 022-001_02 (Service Tools) in Section 2 and 022-001_07 (Service Tools) in Section 7 in Service Manual, Signature™, ISX, and QSX15, Bulletin 3666239. A new cylinder head lifting fixture, Part Number 3400329, replaced the old lifting fixture, Part Number 3162996, in Section 2 and a remote filter head adapter replacer, Part Number 4919518, was added to Section 7.

Related Procedures

10-022-001_02 (/qs3/pubsys2/xml/en/procedures/10/10-022-001_02.html)	Service Tools (/qs3/pubsys2/xml/en/procedures/10/10-022-001_02.html)
10-022-001_07 (/qs3/pubsys2/xml/en/procedures/10/10-022-001_07.html)	Service Tools (/qs3/pubsys2/xml/en/procedures/10/10-022-001_07.html)

Last Modified: 30-Sep-2009