



Technical Service Bulletin

Technical Service Bulletin: tsb103952

Released Date: 28-Sep-2009

Cylinder Head Procedure, Remove and Install Revisions

Cylinder Head Procedure, Remove and Install Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 002-004 (Cylinder Head) in Section 2 in Service Manual, Signature™, ISX, and QSX15, Bulletin 3666329. The addition of a service tool engine lifting fixture, Part Number 4919360, was added to the Remove section. The service tool engine lifting fixture, Part Number 3162996, was changed to Part Number 4919360 in the Install section.

Related Procedures

10-002-004-tr
(/qs3/pubsys2/xml/en/procedures/10/10-002-004-tr.html)

Cylinder Head
(/qs3/pubsys2/xml/en/procedures/10/10-002-004-tr.html)

Last Modified: 28-Sep-2009