



Technical Service Bulletin

Technical Service Bulletin: tsb103981

Released Date: 16-Nov-2009

Injector Procedure, Leak Test Section Revision

Injector Procedure, Leak Test Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the torque value specifications for the fueling and timing actuators in the Leak Test section of Procedure 006-026 (Injector).

Related Procedures

10-006-026-tr
(/qs3/pubsys2/xml/en/procedures/10/10-006-026-tr.html)

Injector
(/qs3/pubsys2/xml/en/procedures/10/10-006-026-tr.html)

Last Modified: 16-Nov-2009