



Technical Service Bulletin

Technical Service Bulletin: tsb104063

Released Date: 29-Jan-2010

Crankshaft Procedure, Multiple Section Revisions

Crankshaft Procedure, Multiple Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the remove and install the thrust bearings to the preparatory and finishing steps. The min/max for crankshaft total runout was revised to a maximum of 0.230 mm [0.009 in]. The maximum adjacent journal runout has been revised to 0.080 mm [0.003 in].

Related Procedures

18-001-016-tr
(/qs3/pubsys2/xml/en/procedures/18/18-001-016-tr.html)

Crankshaft
(/qs3/pubsys2/xml/en/procedures/18/18-001-016-tr.html)

Last Modified: 29-Jan-2010