



Technical Service Bulletin

Technical Service Bulletin: tsb104141

Released Date: 23-Mar-2010

Lubricating Oil Dipstick and Lubricating Oil Leaks, Procedure Additions

Lubricating Oil Dipstick and Lubricating Oil Leaks, Procedure Additions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the lubricating oil section of the K19 Service Manual, Bulletin 4021499, to include procedures for calibrating the oil dipstick and identifying oil leaks.

Related Procedures

18-007-009 (/qs3/pubsys2/xml/en/procedures/18/18-007-009.html)	Lubricating Oil Dipstick (/qs3/pubsys2/xml/en/procedures/18/18-007-009.html)
18-007-024 (/qs3/pubsys2/xml/en/procedures/18/18-007-024.html)	Lubricating Oil Leaks (/qs3/pubsys2/xml/en/procedures/18/18-007-024.html)

Last Modified: 23-Mar-2010