



Technical Service Bulletin

Technical Service Bulletin: TSB130094

Released Date: 17-Jul-2013

Injector Return Flow Specification Change for ISB CM2150, ISB6.7 CM2250, QSB6.7 CM2250, QSB6.7 CM2250 EC and ISB6.7 CM2350

Injector Return Flow Specification Change for ISB CM2150, ISB6.7 CM2250, QSB6.7 CM2250, QSB6.7 CM2250 EC and ISB6.7 CM2350

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document announces the change in the injector return flow specification on the following engines:

Service Model Name and Service Manual and Procedure Numbers Affected		
Service Model Name	Service Manual Bulletin Number	Procedure Number
ISB CM2150	4021578	006-026
ISB6.7 CM2250	4022254	005-236
QSB6.7 CM2250	4022255	005-236
QSB6.7 CM2250 EC	2883621	005-236
ISB6.7 CM2350	2883567	005-236

The reason for the change was determined under a Rapid Problem Solving (RPS) project. Tests were conducted to determine the accurate injector return flow measurement. The new approved maximum injector return flow specification is 150 ml in 30 seconds [5 fluid oz in 30 seconds].

Document History

Date	Details
2013-6-4	Module Created
2013-6-14	Ticket No.: 51084 Reason: Format Error Notes: Please change the specification mentioned in the last line as 5.1 gallons to 5 fl oz

Date	Details
2013-7-17	Ticket No.: 51618 Reason: Format Error Notes: Please remove the RPS project # 'MELR-86UTH3' from the following line in the TSB, 'The reason for the change was determined under a Rapid Problem Solving (RPS) project MELR-86UTH3'. Please call me on 8123431718 if any questions.

Last Modified: 17-Jul-2013
