



Technical Service Bulletin

Technical Service Bulletin: TSB140138

Released Date: 01-Oct-2014

ISX15 and QSX15 Cylinder Liner Shim Supersession

ISX15 and QSX15 Cylinder Liner Shim Supersession

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document announces the supersession of cylinder liner shims used to regain cylinder liner protrusion height after using counterbore cutter kit, Part Number 2892436, to perform a cylinder liner counterbore machining operation on ISX15 and QSX15 engines.

Cylinder liner shim, thickness 0.508 mm [0.020 in], Part Number 2892402, has been obsoleted and superseded by Part Number 5298564.

Cylinder liner shim, thickness 0.813 mm [0.032 in], Part Number 2892403, has been obsoleted and superseded by Part Number 5298565.

Document History

Date	Details
2014-9-29	Module Created

Last Modified: 01-Oct-2014