



Technical Service Bulletin

Technical Service Bulletin: TSB220095

Released Date: 05-May-2022

New Lubricating Oil Pump

New Lubricating Oil Pump

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- ISX CM570
- ISX CM870
- ISX CM871
- ISX CM871 E
- ISX15 CM2250
- ISX15 CM2250 SN
- ISX15 CM2350 X101
- QSX15 CM2250
- QSX15 CM2250 ECF
- QSX15 CM2250 X115
- QSX15 CM2350 X105
- QSX15 CM2350 X106
- QSX15 CM570
- QSX15 CM2350 X118
- QSX15 CM570 X147G
- X15 CM2350 X116B

Description of Change

A new lubricating oil pump is available.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts				
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Lubrication Oil Pump	3687528	No	Yes	5680039
	5532492	No	Yes	
	5599284	No	Yes	
	5679854	No	Yes	
Part Inventory Action				
Use existing part number inventory before using the new part number.				

Document History

Date	Details
2022-5-5	Module Created