



Technical Service Bulletin

Technical Service Bulletin: TSB250138

Released Date: 21-Jul-2025

New Exhaust Manifold Gasket

New Exhaust Manifold Gasket

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSZ13 CM2150 Z102

Description of Change

New exhaust manifold gasket is developed to improve reliability.

Service Instructions

Use new part number for service.

Service Parts

Service parts are offered for Z14 and 15N. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
GASKET, EXHAUST MANIFOLD	2873982	No	No	5580253
GASKET, EXHAUST MANIFOLD	4959925	No	No	5580252

Part Inventory Action

Do **not** use existing part number inventory for QSZ13 CM2150 Z102.

Document History

Date	Details
2025-7-18	Module Created

Last Modified: 21-Jul-2025
