

Trainings ▾

Install

The block stiffener plate use has been discontinued for the QSK45 and QSK60 engines.

Do **not** install the block stiffener plate.

