

Manual Change History (4022094) QSK19 CM2150 and CM2670

Electronic Control System Troubleshooting and Repair Manual

Date	15-Sep-2010
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc2998 (/qs3/pubsys2/xml/en/procedures/123/123-fc2998.html)
Procedure Title	Engine Torque Limit Feature - Special Instructions
Update Reason	Added fault code to outline.
Date	21-Sep-2010
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc2619 (/qs3/pubsys2/xml/en/procedures/123/123-fc2619.html)
Procedure Title	Auxiliary Equipment Sensor Input 1 Engine Protection Critical - Special Instructions
Update Reason	Added fault code to outline.
Date	21-Sep-2010
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-t05-2619 (/qs3/pubsys2/xml/en/procedures/123/123-t05-2619.html)
Procedure Title	Auxiliary Equipment Sensor Input 1 Engine Protection Critical - Special Instructions
Update Reason	Added fault code to outline.
Date	13-Dec-2010
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc1774 (/qs3/pubsys2/xml/en/procedures/123/123-fc1774.html)
Procedure Title	Oil Priming Pump Control Circuit - Voltage Above Normal or Shorted to High Source
Update Reason	New FC1774 added to the Troubleshooting Section.

Date	13-Dec-2010
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-t05-1774 (/qs3/pubsys2/xml/en/procedures/123/123-t05-1774.html)
Procedure Title	Oil Priming Pump Control Circuit - Voltage Above Normal or Shorted to High Source
Update Reason	New FC1774 added to the Troubleshooting Section.

Date	21-Jan-2011
Section	Section F - Familiarization
Procedure Number	00-022-999 (/qs3/pubsys2/xml/en/procedures/00/00-022-999.html)
Procedure Title	Service Tools and Hardware - Overview
Update Reason	Updated General Information, Initial Check, Setup, and Resistance Check sections.

Date	02-Jun-2011
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	123-t02-1001 (/qs3/pubsys2/xml/en/procedures/123/123-t02-1001.html)
Procedure Title	Engine Performance Troubleshooting Tree
Update Reason	Multiple step updates.

Date	11-Jul-2011
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	123-019-390 (/qs3/pubsys2/xml/en/procedures/123/123-019-390.html)
Procedure Title	Turbocharger Speed Sensor
Update Reason	Updated speed sensor wiring routing and clips.

Date	12-Oct-2011
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc1852 (/qs3/pubsys2/xml/en/procedures/123/123-fc1852.html)
Procedure Title	Water-In-Fuel Indicator - Data Valid But Above Normal Operating Range - Moderately Severe Level
Update Reason	Updated Shop Talk

Date	17-Oct-2011
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-t05-197 (/qs3/pubsys2/xml/en/procedures/123/123-t05-197.html)
Procedure Title	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Update Reason	Guided Step 1C, Yes, added: If Fault Code 197 is active and the coolant level is not low, a malfunctioning coolant level sensor is a likely cause. Refer to the OEM service manual before replacing the coolant level sensor.

Date	17-Oct-2011
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-t05-235 (/qs3/pubsys2/xml/en/procedures/123/123-t05-235.html)
Procedure Title	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Update Reason	Guided Step 1A, Yes, added: If Fault Code 235 is active and the coolant level is not low, a malfunctioning coolant level sensor is a likely cause. Refer to the OEM service manual before replacing the coolant level sensor.

Date	08-Dec-2011
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	123-019-115 (/qs3/pubsys2/xml/en/procedures/123/123-019-115.html)
Procedure Title	Rail Fuel Pressure Sensor
Update Reason	Corrected the torque value for the fuel pump pressure sensor.

Date	17-Jan-2012
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc1544 (/qs3/pubsys2/xml/en/procedures/123/123-fc1544.html)
Procedure Title	Auxiliary Pressure Sensor Input 1 - Special Instructions
Update Reason	Updated Shop Talk and circuit descriptions to include Marine specific information.

Date	10-Feb-2012
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	105-019-032 (/qs3/pubsys2/xml/en/procedures/105/105-019-032.html)
Procedure Title	ECM Calibration Code
Update Reason	Updated to include information concerning troubleshooting of ECM calibration issues once new calibration is installed.

Date	01-Jun-2012
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-t05-245 (/qs3/pubsys2/xml/en/procedures/123/123-t05-245.html)
Procedure Title	Fan Control Circuit - Voltage Below Normal or Shorted to Low Source
Update Reason	Changed Step 2B Specifications: Within the OEM resistance specification?

Date	23-Oct-2012
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	123-t02-1001 (/qs3/pubsys2/xml/en/procedures/123/123-t02-1001.html)
Procedure Title	Engine Performance Troubleshooting Tree
Update Reason	Corrected "Next Step" numbering
Date	03-Dec-2012
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-t05-2261 (/qs3/pubsys2/xml/en/procedures/123/123-t05-2261.html)
Procedure Title	Fuel Pump Delivery Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Update Reason	Revised entire fault code.
Date	25-Feb-2013
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-t05-187 (/qs3/pubsys2/xml/en/procedures/123/123-t05-187.html)
Procedure Title	Sensor Supply 2 Circuit - Voltage Below Normal or Shorted to Low Source
Update Reason	Step2E-1 changed the wording from barometric pressure sensor to fuel delivery pressure sensor in conditions.
Date	23-Apr-2013
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-t05-2215 (/qs3/pubsys2/xml/en/procedures/123/123-t05-2215.html)
Procedure Title	Fuel Pump Delivery Pressure - Data Valid But Below Operating Range - Moderately Severe Level
Update Reason	Replaced Guided Steps 2C and 2D and added new Guided Step 2E.

Date	23-Apr-2013
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-t05-2262 (/qs3/pubsys2/xml/en/procedures/123/123-t05-2262.html)
Procedure Title	Fuel Pump Delivery Pressure - Data Valid But Below Operating Range - Least Severe Level
Update Reason	Replaced Guided Steps 2C and 2D and added new Guided Step 2E.

Date	06-Nov-2013
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-t05-1542 (/qs3/pubsys2/xml/en/procedures/123/123-t05-1542.html)
Procedure Title	Auxiliary Pressure Sensor Input 1 Circuit - Voltage Above Normal or Shorted to High Source
Update Reason	Changed fault code numbers in Steps 2B, 2D, and 3E.

Date	06-Nov-2013
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-t05-1543 (/qs3/pubsys2/xml/en/procedures/123/123-t05-1543.html)
Procedure Title	Auxiliary Pressure Sensor Input 1 Circuit - Voltage Below Normal or Shorted to Low Source
Update Reason	Changed fault code numbers in Steps 2C, 3F, and 4A.

Date	31-Jan-2014
Section	Section E - Engine and System Identification
Procedure Number	123-100-002-tr (/qs3/pubsys2/xml/en/procedures/123/123-100-002-tr.html)
Procedure Title	Engine Diagrams
Update Reason	Corrected errors under "Left View".

Date	17-Apr-2014
Section	Section 19 - Electronic Controls
Procedure Number	123-019-031 (/qs3/pubsys2/xml/en/procedures/123/123-019-031.html)
Procedure Title	Engine Control Module
Update Reason	Revise jackscrew torque value and added a note to not over torque.

Date	17-Apr-2014
Section	Section 19 - Electronic Controls
Procedure Number	123-019-043 (/qs3/pubsys2/xml/en/procedures/123/123-019-043.html)
Procedure Title	Engine Wiring Harness
Update Reason	Revise jackscrew torque value and added a note to not over torque.

Date	04-Mar-2015
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc4615 (/qs3/pubsys2/xml/en/procedures/123/123-fc4615.html)
Procedure Title	Fuel Pump Delivery Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Update Reason	Added to outline.

Date	04-Mar-2015
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-ft05-4615 (/qs3/pubsys2/xml/en/procedures/123/123-ft05-4615.html)
Procedure Title	Fuel Pump Delivery Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Update Reason	Added to outline.

Date	07-Apr-2015
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-t05-1911 (/qs3/pubsys2/xml/en/procedures/123/123-t05-1911.html)
Procedure Title	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Update Reason	Updated to include test procedure for electronically actuated injectors.

Date	07-Apr-2015
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-t05-449 (/qs3/pubsys2/xml/en/procedures/123/123-t05-449.html)
Procedure Title	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Update Reason	Updated to include test procedure for electronically actuated injectors.

Date	07-Apr-2015
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-t05-559 (/qs3/pubsys2/xml/en/procedures/123/123-t05-559.html)
Procedure Title	Injector Metering Rail 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Update Reason	Updated to include test procedure for electronically actuated injectors.

Date	07-Apr-2015
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-t05-2215 (/qs3/pubsys2/xml/en/procedures/123/123-t05-2215.html)
Procedure Title	Fuel Pump Delivery Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Update Reason	Updated to include test procedure for electronically actuated injectors.

Date	07-Apr-2015
Section	
Procedure Number	123-t05-2262 (/qs3/pubsys2/xml/en/procedures/123/123-t05-2262.html)
Procedure Title	Fuel Pump Delivery Pressure - Data Valid But Below Operating Range - Least Severe Level
Update Reason	Updated to include test procedure for electronically actuated injectors.

Date	20-Jul-2015
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	123-019-390 (/qs3/pubsys2/xml/en/procedures/123/123-019-390.html)
Procedure Title	Turbocharger Speed Sensor
Update Reason	Corrected the instructions for the turbocharger speed sensor Remove and Install Steps.

Date	24-Sep-2015
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc1852 (/qs3/pubsys2/xml/en/procedures/123/123-fc1852.html)
Procedure Title	Water In Fuel Indicator - Data Valid But Above Normal Operating Range - Moderately Severe Level
Update Reason	Added information on engine derate for marine engines.

Date	24-Sep-2015
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	00-t05-1852 (/qs3/pubsys2/xml/en/procedures/00/00-t05-1852.html)
Procedure Title	Water In Fuel Indicator - Data Valid But Above Normal Operating Range - Moderately Severe Level
Update Reason	Replaced 123-t05-1852.

Date	24-Sep-2015
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc4642 (/qs3/pubsys2/xml/en/procedures/123/123-fc4642.html)
Procedure Title	Water in Fuel Indicator - Data Valid But Above Normal Operating Range - Most Severe Level
Update Reason	Added fault code to manual.

Date	08-Oct-2015
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc5634 (/qs3/pubsys2/xml/en/procedures/123/123-fc5634.html)
Procedure Title	Marine Overload Protection - Condition Exists - Choice
Update Reason	Added to manual.

Date	03-Sep-2015
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc5634aux (/qs3/pubsys2/xml/en/procedures/123/123-fc5634aux.html)
Procedure Title	Marine Overload Protection - Condition Exists
Update Reason	Added to manual.

Date	03-Sep-2015
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc5634prop (/qs3/pubsys2/xml/en/procedures/123/123-fc5634prop.html)
Procedure Title	Marine Overload Protection - Condition Exists
Update Reason	Added to manual.

Date	06-Oct-2015
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc5635 (/qs3/pubsys2/xml/en/procedures/123/123-fc5635.html)
Procedure Title	Marine Overload Protection - Special Instructions - Choice
Update Reason	Added to manual.

Date	06-Oct-2015
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc5635aux (/qs3/pubsys2/xml/en/procedures/123/123-fc5635aux.html)
Procedure Title	Marine Overload Protection - Special Instructions
Update Reason	Added to manual.

Date	06-Oct-2015
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc5635prop (/qs3/pubsys2/xml/en/procedures/123/123-fc5635prop.html)
Procedure Title	Marine Overload Protection - Special Instructions
Update Reason	Added to manual.

Date	17-Nov-2015
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc418 (/qs3/pubsys2/xml/en/procedures/123/123-fc418.html)
Procedure Title	Water in Fuel Indicator - Data Valid But Above Normal Operating Range - Least Severe Level
Update Reason	Added to manual.
Date	17-Nov-2015
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-t05-418 (/qs3/pubsys2/xml/en/procedures/123/123-t05-418.html)
Procedure Title	Water in Fuel Indicator - Data Valid But Above Normal Operating Range - Least Severe Level
Update Reason	Added to manual.
Date	3-Nov-2016
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc5633 (/qs3/pubsys2/xml/en/procedures/123/123-fc5633.html)
Procedure Title	Marine Low Load Protection - Condition Exists - Choice
Update Reason	Added fault code to outline.
Date	3-Nov-2016
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc5633aux (/qs3/pubsys2/xml/en/procedures/123/123-fc5633aux.html)
Procedure Title	Marine Low Load Protection - Condition Exists
Update Reason	Added fault code to outline.

Date	3-Nov-2016
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc5633prop (/qs3/pubsys2/xml/en/procedures/123/123-fc5633prop.html)
Procedure Title	Marine Low Load Protection - Condition Exists
Update Reason	Added fault code to outline.
Date	2-Nov-2016
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	00-t05-5633 (/qs3/pubsys2/xml/en/procedures/00/00-t05-5633.html)
Procedure Title	Marine Low Load Protection - Condition Exists
Update Reason	Added fault code to outline.
Date	05-Dec-2016
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	00-ttecm (/qs3/pubsys2/xml/en/procedures/00/00-ttecm.html)
Procedure Title	ECM - No Communication Troubleshooting Tree
Update Reason	Modified Steps 2, 6, 9 and 11 and added information for new INLINE™ 7 data link.
Date	13-Dec-2016
Section	Section F - Familiarization
Procedure Number	00-022-999 (/qs3/pubsys2/xml/en/procedures/00/00-022-999.html)
Procedure Title	Service Tools and Hardware - Overview
Update Reason	Removed or corrected information for INLINE™ 4, 5, and 6. Added new information for INLINE™ 7 data link.

Date	10-Jan-2017
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc521 (/qs3/pubsys2/xml/en/procedures/123/123-fc521.html)
Procedure Title	Transmission Oil Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Update Reason	Added fault code to manual.

Date	10-Jan-2017
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc522 (/qs3/pubsys2/xml/en/procedures/123/123-fc522.html)
Procedure Title	Transmission Oil Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Update Reason	Added fault code to manual.

Date	10-Jan-2017
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc2562 (/qs3/pubsys2/xml/en/procedures/123/123-fc2562.html)
Procedure Title	Transmission (or Gearbox) Oil Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Update Reason	Added fault code to manual.

Date	10-Jan-2017
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc4688 (/qs3/pubsys2/xml/en/procedures/123/123-fc4688.html)
Procedure Title	Water in Fuel Indicator 2 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Update Reason	Added fault code to manual.

Date	10-Jan-2017
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc4689 (/qs3/pubsys2/xml/en/procedures/123/123-fc4689.html)
Procedure Title	Water in Fuel Indicator 2 Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Update Reason	Added fault code to manual.

Date	10-Jan-2017
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc5366 (/qs3/pubsys2/xml/en/procedures/123/123-fc5366.html)
Procedure Title	Water in Fuel Indicator 2 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Update Reason	Added fault code to manual.

Date	10-Jan-2017
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc5367 (/qs3/pubsys2/xml/en/procedures/123/123-fc5367.html)
Procedure Title	Water in Fuel Indicator 2 - Data Valid But Above Normal Operating Range - Most Severe Level
Update Reason	Added fault code to manual.

Date	10-Jan-2017
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc5932 (/qs3/pubsys2/xml/en/procedures/123/123-fc5932.html)
Procedure Title	Water in Fuel Indicator 2 - Data Valid But Above Normal Operating Range - Least Severe Level
Update Reason	Added fault code to manual.

Date	10-Jan-2017
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc5946 (/qs3/pubsys2/xml/en/procedures/123/123-fc5946.html)
Procedure Title	Transmission (or Gearbox) Oil Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Update Reason	Added fault code to manual.
Date	21-Apr-2017
Section	Section 19 - Electronic Controls
Procedure Number	123-019-067 (/qs3/pubsys2/xml/en/procedures/123/123-019-067.html)
Procedure Title	Engine Oil Temperature Sensor
Update Reason	Added procedure to manual.
Date	01-Nov-2018
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-t05-1911 (/qs3/pubsys2/xml/en/procedures/123/123-t05-1911.html)
Procedure Title	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Update Reason	Added the missing link to the step 2A- QSK19 service manual procedure 006-003.
Date	03-Nov-2021
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-t05-351 (/qs3/pubsys2/xml/en/procedures/123/123-t05-351.html)
Procedure Title	Injector Power Supply - Bad Intelligent Device or Component
Update Reason	Removed instruction to disconnect the ECM power supply harness from the battery terminals in step 2C.

Date	02-Sep-2025
Section	Back
Procedure Number	4022094-history (/qs3/pubsys2/xml/en/manual/4022094/4022094-history.html)
Procedure Title	Manual Change History
Update Reason	Added QSK19 CM2670 MCRS C to manual change history, outline and titlepage.

Date	06-Feb-2026
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc187 (/qs3/pubsys2/xml/en/procedures/123/123-fc187.html)
Procedure Title	Sensor Supply 2 Circuit - Voltage Below Normal or Shorted to Low Source
Update Reason	Updated the troubleshooting for Fault Code 187 to call out the correct components on the correct sensor supply. Aligns with wiring diagram change submitted as well.

Date	06-Feb-2026
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-t05-187 (/qs3/pubsys2/xml/en/procedures/123/123-t05-187.html)
Procedure Title	Sensor Supply 2 Circuit - Voltage Below Normal or Shorted to Low Source
Update Reason	Updated the troubleshooting for Fault Code 187 to call out the correct components on the correct sensor supply. Aligns with wiring diagram change submitted as well.

Date	06-Feb-2026
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc227 (/qs3/pubsys2/xml/en/procedures/123/123-fc227.html)
Procedure Title	Sensor Supply 2 Circuit - Voltage Above Normal or Shorted to High Source
Update Reason	Updated the troubleshooting for Fault Code 227 to call out the correct components on the correct sensor supply. Aligns with wiring diagram change submitted as well.

Date	06-Feb-2026
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-t05-227 (/qs3/pubsys2/xml/en/procedures/123/123-t05-227.html)
Procedure Title	Sensor Supply 2 Circuit - Voltage Above Normal or Shorted to High Source
Update Reason	Updated the troubleshooting for Fault Code 227 to call out the correct components on the correct sensor supply. Aligns with wiring diagram change submitted as well.

Date	06-Feb-2026
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc2185 (/qs3/pubsys2/xml/en/procedures/123/123-fc2185.html)
Procedure Title	Sensor Supply 4 Circuit - Voltage Above Normal or Shorted to High Source
Update Reason	Updated the troubleshooting for Fault Code 2185 to call out the correct components on the correct sensor supply. Aligns with wiring diagram change submitted as well.

Date	06-Feb-2026
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-t05-2185 (/qs3/pubsys2/xml/en/procedures/123/123-t05-2185.html)
Procedure Title	Sensor Supply 4 Circuit - Voltage Above Normal or Shorted to High Source
Update Reason	Updated the troubleshooting for Fault Code 2185 to call out the correct components on the correct sensor supply. Aligns with wiring diagram change submitted as well.
Date	06-Feb-2026
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-fc2186 (/qs3/pubsys2/xml/en/procedures/123/123-fc2186.html)
Procedure Title	Sensor Supply 4 Circuit - Voltage Below Normal or Shorted to Low Source
Update Reason	Updated the troubleshooting for Fault Code 2186 to call out the correct components on the correct sensor supply. Aligns with wiring diagram change submitted as well.
Date	06-Feb-2026
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	123-t05-2186 (/qs3/pubsys2/xml/en/procedures/123/123-t05-2186.html)
Procedure Title	Sensor Supply 4 Circuit - Voltage Below Normal or Shorted to Low Source
Update Reason	Updated the troubleshooting for Fault Code 2186 to call out the correct components on the correct sensor supply. Aligns with wiring diagram change submitted as well.