



Technical Service Bulletin

Technical Service Bulletin: tsb100077	Released Date: 21-Feb-2005
Cylinder Head Torque For New Block and Capscrews	

Cylinder Head Torque For New Block and Capscrews

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin has been superseded by Service/Parts Topic 99T2-6.
--

Last Modified: 21-Feb-2005
