



Technical Service Bulletin

Technical Service Bulletin: tsb100701

Released Date: 23-May-2008

New Connecting Rod


New Connecting Rod

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin announces the release of a new connecting rod to be used on all 8.3 liter engines.



Old Connecting Rod Bushing (left) and New Connecting Rod Bushing (right)

The new connecting rod has a newly designed bushing oil groove. Connecting rods with the old and new style bushings can be mixed within the same engine.

The table below identifies the part number and engine serial number (ESN) first for the old and new connecting rods.

Old Part Number	New Part Number	Engine Serial Number (ESN) First	Description
3971394	4947898	46889300	Rod, engine connecting

Last Modified: 23-May-2008
