



Technical Service Bulletin

Technical Service Bulletin: tsb100908

Released Date: 10-Mar-2010

New Oil Pan Options

New Oil Pan Options

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin announces a new range of oil pan options for certain B and C Series engines that have previously utilized isolated mounting capscrews.

The new options provide a more robust oil pan assembly with improved sealing characteristics.

These new options do **not** utilize isolated mounting capscrews; these isolators are now obsolete for production.

If any of the previous option components are to be replaced in the field, the original replacement parts remain available for service **only**.

The oil pan capscrews are **not** interchangeable.

The following oil pan part numbers obsolete and supersede the original part numbers for production **only**.

Oil Pan Part Number to be Obsoleted in Production	Oil Pan Option Number to be Obsoleted in Production	Description	New Oil Pan Part Number	New Oil Pan Option Number
3931277	OP 9112	Pan, Oil	3930460	OP 9613
3931277	OP 9113	Pan, Oil	3930460	OP 9614
3940434	OP 9118	Pan, Oil	3914015	OP 9603
3930282	OP 9126	Pan, Oil	3352546	OP 9604
3930282	OP 9127	Pan, Oil	3352546	OP 9605
3283449	OP 9151	Pan, Oil	3282305	OP 9606
3931277	OP 9163	Pan, Oil	3930460	OP 9615

Oil Pan Part Number to be Obsoleted in Production	Oil Pan Option Number to be Obsoleted in Production	Description	New Oil Pan Part Number	New Oil Pan Option Number
3930434	OP 9357	Pan, Oil	3914015	OP 9607
3930434	OP 9358	Pan, Oil	3914015	
3930282	OP 9365	Pan, Oil	3352546	
3931277	OP 9385	Pan, Oil	3930460	
3930282	OP 9394	Pan, Oil	3352546	
3930282	OP 9410	Pan, Oil	3352546	
3944262	OP 9436	Pan, Oil	3974294	
3931277	OP 9488	Pan, Oil	3930460	
n/a	OP 9718	Mounting, Oil Pan	n/a	
n/a	OP 9719	Mounting, Oil Pan	n/a	
n/a	OP 9743	Mounting, Oil Pan	n/a	
n/a	OP 9389	Mounting, Oil Pan	n/a	
				OP 9608
				OP 9609
				OP 9616
				OP 9610
				OP 9611
				OP 9612
				OP 9618
				OP 9619
				OP 9620
				OP 9621
				OP 9617

Be sure to follow the correct removal and installation procedures, including torque values and sequences, when replacing the oil pan.