



Technical Service Bulletin

Technical Service Bulletin: TSB101035

Released Date: 26-Feb-2020

Rear Crankshaft Seal Part Number Supersession

Rear Crankshaft Seal Part Number Supersession

Core Issue

Confirmation

Resolution

See Technical Service Bulletin, New Rear Crankshaft Seal Service Tools, TSB180112.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Document History

Date	Details
2010-8-17	Module Created
2020-2-26	Removed all content and added reference to TSB180112.

Last Modified: 26-Feb-2020