



Technical Service Bulletin

Technical Service Bulletin: tsb101170	Released Date: 03-Sep-2002
Engine Compression, Measure	

Engine Compression, Measure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic releases new procedure, Engine Compression, Procedure Number 014-012, which will be used in the C8.3 Troubleshooting and Repair Manuals, Bulletins 3666003 and 3810261, and also revises the next to the last node in Symptom Tree T057 to include reference to the new procedure.

Last Modified: 03-Sep-2002
