



Technical Service Bulletin

Technical Service Bulletin: tsb101194	Released Date: 05-Sep-2002
Mechanical Lift Pump Test Procedure	

Mechanical Lift Pump Test Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic updates Procedure 005-045, Fuel Lift Pump, for the C8.3 series engines.
--

Last Modified: 05-Sep-2002
