



Technical Service Bulletin

Technical Service Bulletin: tsb101195	Released Date: 25-Sep-2002
Centinel™ Oil Control Valve	

Centinel™ Oil Control Valve

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic revises Procedure 007-078, Centinel™ Oil Control Valve.
--

Last Modified: 25-Sep-2002
