



Technical Service Bulletin

Technical Service Bulletin: tsb101302

Released Date: 12-Feb-2004

Procedure 011-009, Exhaust Restriction

Procedure 011-009, Exhaust Restriction

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic revises Procedure 011-009, Exhaust Restriction to include Marine application information for the C Series Troubleshooting and Repair Manual, Bulletin 3666003.

Related Procedures

41-011-009
(/qs3/pubsys2/xml/en/procedures/41/41-011-009.html)

Exhaust Restriction
(/qs3/pubsys2/xml/en/procedures/41/41-011-009.html)

Last Modified: 12-Feb-2004