



# Technical Service Bulletin

Technical Service Bulletin: tsb101303

Released Date: 02-Sep-2003

Procedure 001-089, Block Stiffener Plate

## Procedure 001-089, Block Stiffener Plate

### Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

This service/parts topic introduces the block stiffener plate for C8.3G, C Gas Plus, 6C, and C8.3 series engines. This topic also assists repair and service personnel in removal and installation procedures.

**Note :** This is a product improvement and is not subject to campaign.

### Related Procedures

100-001-089  
(/qs3/pubsys2/xml/en/procedures/100/100-001-089.html)

Block Stiffener Plate  
(/qs3/pubsys2/xml/en/procedures/100/100-001-089.html)

Last Modified: 02-Sep-2003