



Technical Service Bulletin

Technical Service Bulletin: tsb101314

Released Date: 13-Oct-2003

Revised Fuel System Procedures, 005-012 and 005-999

Revised Fuel System Procedures, 005-012 and 005-999

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic revises Procedures, 005-012 and 005-999 for the C6 and C8.3 engine series.

Related Procedures

41-005-012 (/qs3/pubsys2/xml/en/procedures/41/41-005-012.html)	Fuel Injection Pumps, In-Line (/qs3/pubsys2/xml/en/procedures/41/41-005-012.html)
41-005-999 (/qs3/pubsys2/xml/en/procedures/41/41-005-999.html)	Fuel System - Overview (/qs3/pubsys2/xml/en/procedures/41/41-005-999.html)

Last Modified: 13-Oct-2003