



Technical Service Bulletin

Technical Service Bulletin: tsb101315	Released Date: 09-Feb-2004
Revision to Troubleshooting Trees	

Revision to Troubleshooting Trees

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises troubleshooting trees for C Series engines.
--

Alternator Not Charging or Insufficient Charging Alternator Overcharging Coolant Loss Coolant Temperature Above Normal - Gradual Overheat Coolant Temperature Above Normal - Sudden Overheat Coolant Temperature Above Normal - Sea Water Cooling System Engine Acceleration or Response Poor Engine Difficult to Start or Will Not Start (Exhaust Smoke) Engine Difficult to Start or Will Not Start (No Exhaust Smoke) Engine Power Output Low Engine Runs Rough at Idle Engine Vibration Excessive Engine Will Not Reach Rated Speed (RPM) Intake Manifold Air Temperature Above Specification Intake Manifold Pressure (Boost) is Below Normal Lubricating Oil Consumption Excessive Smoke, Black - Excessive Smoke, White - Excessive

Last Modified: 09-Feb-2004
