



Technical Service Bulletin

Technical Service Bulletin: tsb101317

Released Date: 15-Sep-2003

Revision to Procedure 007-025, Lubricating Oil Pan

Revision to Procedure 007-025, Lubricating Oil Pan

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic revises Procedure 007-025, Lubricating Oil Pan for:

- C Series Engines Troubleshooting and Repair Manual, Bulletin 3666003
- C8.3 (Natural Gas) Base Engine Troubleshooting and Repair Manual, Bulletin 3666206.

Related Procedures

100-007-025
(/qs3/pubsys2/xml/en/procedures/100/100-007-025.html)

Lubricating Oil Pan
(/qs3/pubsys2/xml/en/procedures/100/100-007-025.html)

Last Modified: 15-Sep-2003