



Technical Service Bulletin

Technical Service Bulletin: tsb101335

Released Date: 13-Oct-2003

Revision to Procedure 007-035, Lubricating Oil Suction Tube (Block-Mounted)

Revision to Procedure 007-035, Lubricating Oil Suction Tube (Block-Mounted)

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This is product improvement and is **not** subject to campaign.

Related Procedures

100-007-035
(/qs3/pubsys2/xml/en/procedures/100/100-007-035.html)

Lubricating Oil Suction Tube (Block-Mounted)
(/qs3/pubsys2/xml/en/procedures/100/100-007-035.html)

Last Modified: 13-Oct-2003