



Technical Service Bulletin

Technical Service Bulletin: tsb101341

Released Date: 06-Nov-2003

Revised Procedure 006-026, Injector

Revised Procedure 006-026, Injector

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure, 006-026, Injector.

Related Procedures

41-006-026
(/qs3/pubsys2/xml/en/procedures/41/41-006-026.html)

Injector
(/qs3/pubsys2/xml/en/procedures/41/41-006-026.html)

Last Modified: 06-Nov-2003