



Technical Service Bulletin

Technical Service Bulletin: tsb101390

Released Date: 27-Feb-2004

Revision to Procedure 001-014, Connecting Rod

Revision to Procedure 001-014, Connecting Rod

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic documents revisions to Procedure 001-014, Connecting Rod in the C8.3 Gas Base Engine Troubleshooting and Repair Manual and C Series Troubleshooting and Repair Manual.

Related Procedures

100-001-014

(/qs3/pubsys2/xml/en/procedures/100/100-001-014.html)

Connecting Rod

(/qs3/pubsys2/xml/en/procedures/100/100-001-014.html)

Last Modified: 27-Feb-2004