



Technical Service Bulletin

Technical Service Bulletin: tsb101405

Released Date: 22-Mar-2004

Revision to Procedure 007-003, Lubricating Oil Cooler

Revision to Procedure 007-003, Lubricating Oil Cooler

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic is a revision to Procedure 007-003, Lubricating Oil Cooler. The leak test kit, Part Number 3823876, has been included in the leak test step. The torque values for the lubricating oil cooler capscrews have changed in the install step.

Related Procedures

100-007-003
(/qs3/pubsys2/xml/en/procedures/100/100-007-003.html)

Lubricating Oil Cooler
(/qs3/pubsys2/xml/en/procedures/100/100-007-003.html)

Last Modified: 22-Mar-2004