



# Technical Service Bulletin

---

|                                                       |                            |
|-------------------------------------------------------|----------------------------|
| Technical Service Bulletin: tsb101430                 | Released Date: 19-May-2004 |
| Revision to Procedure 010-031, Air Intake Restriction |                            |

## Revision to Procedure 010-031, Air Intake Restriction

### Warranty Statement

---

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

---

This Service/Parts Topic is a revision to Procedure 010-031, Air Intake Restriction. The air intake restriction specification was updated.

### Related Procedures

---

|                                                                      |                                                                                 |
|----------------------------------------------------------------------|---------------------------------------------------------------------------------|
| 100-010-031<br>(/qs3/pubsys2/xml/en/procedures/100/100-010-031.html) | Air Intake Restriction<br>(/qs3/pubsys2/xml/en/procedures/100/100-010-031.html) |
|----------------------------------------------------------------------|---------------------------------------------------------------------------------|

---

**Last Modified: 19-May-2004**

---