



# Technical Service Bulletin

Technical Service Bulletin: tsb101433

Released Date: 24-May-2004

Revision to Procedure 010-033, Turbocharger

## Revision to Procedure 010-033, Turbocharger

### Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

The purpose of this Service/Parts Topic is to update Procedure 010-033 with improved troubleshooting and repair steps.

### Related Procedures

41-010-033  
(/qs3/pubsys2/xml/en/procedures/41/41-010-033.html)

Turbocharger  
(/qs3/pubsys2/xml/en/procedures/41/41-010-033.html)

Last Modified: 24-May-2004