



Technical Service Bulletin

Technical Service Bulletin: tsb101589

Released Date: 26-Jan-2005

Revision to Lubricating Oil Suction Tube (Block Mounted)

Revision to Lubricating Oil Suction Tube (Block Mounted)

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 007-035, Lubricating Oil Suction Tube (Block Mounted), updating the capscrew torque information.

Note : This is a product improvement and not subject to campaign.

Related Procedures

100-007-035
(/qs3/pubsys2/xml/en/procedures/100/100-007-035.html)

Lubricating Oil Suction Tube (Block-Mounted)
(/qs3/pubsys2/xml/en/procedures/100/100-007-035.html)

Last Modified: 26-Jan-2005