



Technical Service Bulletin

Technical Service Bulletin: tsb101640

Released Date: 11-Jul-2005

Revision to Fuel Injection Pump, In-Line

Revision to Fuel Injection Pump, In-Line

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic provides information on the revision of Procedure 005-012 (/qs3/pubsys2/xml/en/procedures/41/41-005-012.html), Fuel Injection Pump, In-Line for the 6C and C8.3 series engines. The fuel pump gear puller service tool has been revised.

Note : This is a product improvement and not subject to campaign.

Related Procedures

41-005-012

(/qs3/pubsys2/xml/en/procedures/41/41-005-012.html)

Fuel Injection Pumps, In-Line

(/qs3/pubsys2/xml/en/procedures/41/41-005-012.html)

Last Modified: 11-Jul-2005