



Technical Service Bulletin

Technical Service Bulletin: tsb101669

Released Date: 19-May-2005

Piston Protrusion

Piston Protrusion

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic is being issued to correct the specifications for Piston Protrusion for Emission Controlled Engines published in Procedure 001-054 of the troubleshooting and repair manual.

Note : This is a product improvement not subject to campaign.

Related Procedures

41-001-054
(/qs3/pubsys2/xml/en/procedures/41/41-001-054.html)

Piston and Connecting Rod Assembly
(/qs3/pubsys2/xml/en/procedures/41/41-001-054.html)

Last Modified: 19-May-2005