



Technical Service Bulletin

Technical Service Bulletin: tsb101692

Released Date: 11-Jul-2005

Revision to Service Tools Procedures

Revision to Service Tools Procedures

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic provides information on the revision of Procedure 022-001 (/qs3/pubsys2/xml/en/procedures/41/41-022-001.html), Service Tools for the 6C and C8.3 series engines. A new service tool has been released to remove the fuel pump gear.

Note : This is a product improvement and not subject to campaign.

Related Procedures

41-022-001_05
(/qs3/pubsys2/xml/en/procedures/41/41-022-001_05.html)

Service Tools
(/qs3/pubsys2/xml/en/procedures/41/41-022-001_05.html)

Last Modified: 11-Jul-2005